

N/A

VISUAL TANK INSPECTION REPORT

N/A

Vessel : ETT-110
Port/Terminal: Hercules Shipyard / Freeport, Texas
Product/Cargo: Cyclohexane

Tank
Number 1C 2C 3C

N/A

Last
Cargo Cyclohexane Cyclohexane Cyclohexane

Second Last

Cargo
Third Last

Coating

Tank

Cargo
Visual Cleanliness

 Visual Cleanliness
 Accepted *
 Accepted
 Accepted

 Visual Cleanliness
 Rejected *
 1540
 1540

 Time/Date
 1540
 1540
 11/30/96

 Inspected
 11/30/96
 11/30/96
 11/30/96

Method said to have been used to clean tanks: Strip and blow: Stripped chemical from cargo tanks and pipe line, blow dry cargo tanks for 30 minutes each, blow dry pipe line for 20 minutes each valve.

Information regarding previous cargoes, tank coating and cleaning method was obtained from vessel personnel and cannot be guaranteed as accurate by Caleb Brett U.S.A., Inc. and no liability can be assumed for errors resulting from improper information supplied. This report, of necessity, is based on such information.

I T S-Caleb Brott

^{*} The cleanliness of inspected tank(s) is/are based on visual inspection of tank surfaces and line system at accessible areas only. This document does not cover the cleanliness of tank surfaces and line system at inaccessible spots and/or possible release of components of previous cargoes during loading, discharge or transport of the cargo in question, for which the vessel is fully responsible. Suitability of tank coating for intended cargo must be guaranteed by vessel's owner or by suppliers of the coating.